



**PROFESSIONAL  
FACILITIES  
MANAGEMENT**



**Haitian Recovery &  
Rebuilding Effort**



## Offering to Prime Contractors in Haitian Recovery & Rebuilding Effort

### PHASE 1: RECOVERY

#### Food Distribution

- ◆ In conjunction with Calhoun Enterprises
- ◆ Product Acquisition
- ◆ Delivery Logistics

#### Construction-related Support Services

- ◆ Labor
- ◆ Equipment Management
- ◆ Logistical Support

#### Facility Management Services

- ◆ Adverse Weather Preparation & Response

#### Administration

- ◆ Computerized Maintenance Management Systems (CMMS)
- ◆ Staffing
- ◆ Personnel Administration
- ◆ Payroll Control
- ◆ Uniforms
- ◆ Badging

#### Support Services

- ◆ Laundry
- ◆ Warehousing
- ◆ Mobile/Temporary Housing Management
- ◆ Mobile Equipment
- ◆ Off-road Vehicles
- ◆ GPS Equipment

### PHASE 2: REBUILDING

#### Food Distribution

- ◆ Punchlist Management
- ◆ Temporary Structures
- ◆ Temporary Employment Services

#### Warehousing

#### Building Remediation

#### Administration

- ◆ Staffing
- ◆ Personnel Administration
- ◆ Payroll Control
- ◆ Uniforms
- ◆ Badging

#### Support Services

- ◆ Laundry
- ◆ Warehousing
- ◆ Mobile/Temporary Housing Management
- ◆ Mobile Equipment
- ◆ Off-road Vehicles
- ◆ GPS Equipment

#### Facility Maintenance Services

- ◆ Janitorial/Housekeeping
- ◆ Landscaping Management
- ◆ Repair & Maintenance (CMMS)
- ◆ Energy Management
- ◆ Adverse Weather Preparation & Response

### CASE STUDY: PRATTVILLE, AL February 17, 2008

On a late afternoon Feb. 18th, 2008 Prattville, AL experienced a local environmental disaster as a tornado, accompanied by heavy rain and strong winds, ripped through several businesses including this K-Mart (*see above*) in the Prattville Shopping Center around 9:30 AM. PFMI associates, from the VP to the service techs, were called in and immediately began securing electrical and water supplies, working hand in hand with the Sheriff, local police and fire departments. Meanwhile, others were contacting rental companies to get lighting, generators, porta potties, dumpsters, and bobcats delivered as soon as possible and securing damaged areas with temporary barricades.

After a law enforcement-imposed curfew PFMI crews, alongside its sub contractors, returned to set up an Aronov command post. Within that first week, PFMI and the rest of the volunteers made significant progress and paved the way for Aronov and its contractors to begin the restoration process.